#### **DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.15

## SOURCE INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** SIR-000118 Address: 333 Burma Road **Date Inspected:** 15-Sep-2007

City: Oakland, CA 94607

**OSM Arrival Time:** 900 **Project Name:** SAS Superstructure **OSM Departure Time:** 1600 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Contractor: Location:** Shanghai China

**Quality Control Contact: Quality Control Present:** Yes Wu Min/DU Wong No

**Material transfer:** Yes N/A **Sampled Items:** Yes No No N/A **Stock Transfer:** N/A N/A Yes No OK to Cut: Yes No **Rebar Test Witness:** Yes No N/A **Delayed/Cancelled:** Yes No N/A

Other:

**Bridge No:** 34-0006 Steel Plate **Component:** 

**Bid Item:** Lot No: 52 (F) B59-130-07/B59-131-07

#### **Summary of Items Observed:**

The Caltrans QA representative Roscoe Dixon arrived at Zhenhua Port steel fabrication welding shop (ZPMC) of Shanghai, China to periodically monitor Quality Control (QC) functions. While on site the QA Inspector met with QC personnel Wu Min and DU Wong at the plate yard, where the QA inspector verified material for visual condition and matched heat numbers with material heat numbers listed on the batch documents provided to the QA inspector by American Bridge/Fluor (ABF).

#### Material Test Reports:

Quality Assurance (QA) Inspector Roscoe Dixon observed material received in the ZPMC yard identified as batch #14 according to the documents received from the QC personnel. There were a total of 35 out of 89 plates received with plate thicknesses ranging from 10mm to 20mm. The plates were all ASTM A709-345T2, ASTM A709M-345T2-X, A709-345F2-X and ASTM A709M-345T2-X-S plate material and were accompanied with material test reports (MTR). The (MTR) s could not be reviewed on the day the plates were observed for their general condition and markings but will be reviewed at the earliest opportunity. QA Inspector Dixon assigned lot number B59-130-07 to this lot of plate.

#### Material Test Reports:

Quality Assurance (QA) Inspector Roscoe Dixon observed material received in the ZPMC yard identified as batch #15 according to the documents received from the QC personnel. There were a total of 18 out of 72 plates received with plate thicknesses ranging from 10mm to 20mm. The plates were all ASTM A709-345T2, ASTM A709M-345T2-X and ASTM A709M-345T2-X-S plate material and were accompanied with material test reports (MTR). The (MTR) s could not be reviewed on the day the plates were observed for their general condition and

# SOURCE INSPECTION REPORT

(Continued Page 2 of 2)

markings but will be reviewed at the earliest opportunity. QA Inspector Dixon assigned lot number B59-131-07 to this lot of plate.

### **Summary of Conversations:**

All relevant work related conversations are as noted within the report shown above.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Dixon,Roscoe	Quality Assurance Inspector
Reviewed By:	Cochran,Jim	QA Reviewer